



**CALIFORNIA UNDERGROUND SAFETY BOARD
INVESTIGATION DIVISION**

INVESTIGATION REPORT

Date: March 11, 2025

Case No.: N2427573

Violations:

Selvin Ramirez Plumbing

Government Code § 4216.2(b): Excavating without first notifying the Regional Notification Center of intent to excavate.

Government Code § 4216. 4(c)(1): Failure to call 911 emergency services upon discovering or causing damage to subsurface installation resulting in the escape of flammable, toxic, or corrosive gas or liquid.

Executive Summary:

On September 24, 2024, at 12:29 p.m., Selvin Ramirez Plumbing excavated without first contacting the Regional Notification Center and damaged a natural gas facility while digging to install a sewer. Selvin Ramirez Plumbing did not call 911 emergency services to report the damage. No one was injured and no equipment, other than the natural gas facility, was damaged.

Reporting Party Information:

Southern California Gas Company
555 West 5th Street
Los Angeles, 90013

Date of Incident:

September 24, 2024

Location of the Incident:

1226 West 70th Street
Los Angeles, California 90044

Operator:

Southern California Gas Company
555 West 5th Street
Los Angeles, 90013

Excavator:

Selvin Ramirez Plumbing
941 East Vernon Avenue
Los Angeles, 90011

Facility Type Damaged:

½" plastic natural gas facility

Investigation:**Notification of the Incident**

On October 11, 2024, at 1:49 p.m. Southern California Gas Company submitted a notification of an incident to the California Underground Safety Board. The notification stated, "Selvin Ramirez plumbing was excavating to install new sewer line for ADU when 1/2" plastic natural gas service was struck with chipping gun resulting in gas escape." (Exh. 1.)

The case was assigned to Investigator Angel Barton (Investigator).

Identity of the Excavator

Government Code section 4216(h) defines an excavator to be "any person, firm, contractor or subcontractor, owner, operator, utility, association, corporation, partnership, business trust, public agency, or other entity that, with their own employees or equipment, performs any excavation."

On September 24, 2024, Jose Ramirez, an apprentice with Selvin Ramirez Plumbing was digging with a shovel and damaged a plastic gas line at 1226 West 70th Street, Los Angeles, California 90044. (Exh. 2.)

Selvin Ramirez Plumbing, as of November 20, 2024, was not licensed by the California Contractors State License Board. Additionally, Selvin Ramirez Plumbing responded "N/A" when asked for its California Contractors State License Board Number. (Exh. 2.)

Selvin Ramirez Plumbing Did Not Contact the Regional Notification Center Before Digging

Government Code section 4216.2(b) states that an excavator planning to excavate shall notify the appropriate regional notification center of the excavator's intent to excavate at least two working days, and not more than 14 calendar days, before beginning that excavation.

Selvin Ramirez Plumbing did not notify the Regional Notification Center before digging at 1226 West 70th Street, Los Angeles, California 90044. The reason that Owner Selvin Ramirez of

Selvin Ramirez Plumbing gave for not contacting the Regional Notification Center was, “I didn’t know what number to call and I’m still learning.” (Exh. 2.)

On November 6, 2024, Investigator emailed Amber Dahl, Safety Awareness Director at DigAlert, requesting ticket information for 1226 West 70th Street, Los Angeles, California 90044, between August 24, 2024, and October 10, 2024. (Exh. 3.)

Safety Awareness Director, Amber Dahl, responded on November 07, 2024, confirmed that a ticket did not exist for 1226 West 70th Street, Los Angeles, California 90044 on September 24, 2024, before the incident occurred. (Exh. 4.)

Selvin Ramirez Plumbing Did Not Call 911 Emergency Services Upon Gas Release

Government Code section 4216.4(c)(1) states an excavator shall call 911 emergency services upon discovering or causing damage to a gas or hazardous liquid pipeline subsurface installation in which the damage results in the escape of any flammable, toxic, or corrosive gas or liquid.

On September 24, 2024, at approximately 12:29 p.m., Selvin Ramirez Plumbing damaged a ½" plastic natural gas facility when excavating by digging to install a sewer. The damage caused gas to leak. Owner Selvin Ramirez of Selvin Ramirez Plumbing answered “no” when asked if anyone with Selvin Ramirez Plumbing called 911 on September 24, 2024, after the damage. (Exh. 2.)

Findings:

1. On September 24, 2024, at 1226 West 70th Street, Los Angeles, California 90044, Selvin Ramirez Plumbing excavated without first notifying the Regional Notification Center.
2. On September 24, 2024, Selvin Ramirez Plumbing failed to call 911 emergency services to report the escaping gas from the subsurface installation after they damaged it while excavating.

Investigator	Supervisor
Angel Barton	Daysi Alcantar
Signature	Signature
/s/ Angel Barton	/s/ Daysi Alcantar

Exhibit List:

Exhibit No.	Description	Date	Received From
1.	Incident Report submitted to the Underground Safety Board	Received on 10/11/2024, at 1:49 p.m.	Southern California Gas Company
2.	Board's Investigation Questionnaire submitted to Owner Selvin Ramirez, Selvin Ramirez Plumbing	Received on 11/18/2024	
3.	Investigator's email to DigAlert requesting ticket information on the underlying job to this incident	Emailed on 11/06/2024	
4.	Email from DigAlert stating there was no valid ticket for the underlying job to this incident	Received on 11/07/2024	Amber Dahl Safety Awareness Director DigAlert

Exhibit 1

No-Ticket Damage Reporting Form

Submitted: October 11, 2024 1:49 PM

Reporter Information

Provide the names, titles, phone numbers, and email addresses of all individuals who are involved in reporting this damage or contributing to the answers to these questions

Full Name

Sean O'Connor

Title

Damage Prevention Analyst

Phone Number

310-683-9471

E-mail address

soconnor@socalgas.com

Company

Provide the name, address, phone number, email address, and, if applicable, the Regional Notification Center (member code for your company).

Company Name

SoCalGas

Address

555 W 5th St., Los Angeles , 90013

Phone Number

310-683-9471

Email Address

SCGDamagePrevention@socalgas.com

Regional Notification Center member code

Other Contacts

Is the photographer same as the primary reporter named above?

Yes

Incident Information

What was the date and approximate time of the incident?

September 24, 2024 12:29 PM

What is the address where your facility was damaged on 9/24/2024?

Damage Street Address

1226 W 70th St

Damage County

Los Angeles

Damage City

Los Angeles

Damage Cross Street 1

Budlong Ave

Damage Cross Street 2

Raymond Ave

Other Damage location description

Does SoCalGas own, operate or maintain the facility damaged on 9/24/2024?

Yes

What type of excavation did you observe on 9/24/2024 at that address?

Sewer

Describe the excavation activity you identified.

3rd party contractor excavating without a USA ticket for sewer install for ADU build struck 1/2" plastic Natural gas service resulting in the escape of gas.

What excavation companies did you observe on 9/24/2024?

Company Name

SELVIN RAMIREZ PLUMBING

Company Address

941 E. VERNON AVE, Los Angeles , 90011

Phone Number

323-423-8740

Email Address

deebuilz@yahoo.com

Did this company damage the facility?

Yes

Provide the name, title, phone number, and email address for at least one contact for each excavation company working at or near incident address on date of incident. If you have more than one contact, please provide all of them. Email addresses are required for submission of this form.

Personnel Name

Selvin Ramirez

Title

Owner

Phone Number

323-423-8740

Email Address

deebuilz@yahoo.com

Notification Details

Was SoCalGas notified of the proposed excavation by the Regional Notification Center before 9/24/2024?

No

What date and time did you learn of the damage to the facility?

September 24, 2024 12:29 PM

How did SoCalGas learn of the damage to the facility?

Intercompany Email Notification

Facility Damaged

What kind of facility was damaged on 9/24/2024?

Natural Gas

Natural Gas

What type of material was the damaged facility?

Plastic

Facility diameter (inches)?

0.5

Incident Details

What kinds of excavation equipment did you observe at the location of the damaged facility?

Powered hand-held other

Do you know what equipment damaged the facility?

Yes

What equipment damaged the facility?

Powered hand-held other

What information are you relying on regarding damage to the facility?

Photographs, Interview with excavator

Did SoCalGas contact the Regional Notification Center before repairing the damaged facility?

No

Provide any other relevant information about the damage on 9/24/2024.

Selvin Ramirez plumbing was excavating to install new sewer line for ADU when 1/2" plastic natural gas service was struck with chipping gun resulting in gas escape.

Damages

Were there any injuries to any personnel or bystanders due to the damage to your facility on 9/24/2024?

No

Was any property damaged other than the damaged facility?

No

Was there a fire caused by this damage on 9/24/2024?

No

Was there an evacuation of any nearby homes or businesses caused by this damage on 9/24/2024?

No

Provide an estimate of the number of your customers whose service was interrupted by this damage on 9/24/2024.

0

Conclusions

What date and time were repairs completed to the damaged facility?

September 24, 2024 2:52 PM

Please explain why you think the facility was damaged on 9/24/2024?

1/2" plastic gas service was damaged resulting in gas escape.

Is there any other information which you feel is important to share about this incident?

Not counting your answers to these questions, did SoCalGas create an investigatory or incident report pertaining to the damage on 9/24/2024?

Yes

Please attach investigatory or incident report here.

USB SelvinRamirezPlumbing 9242024.docx, 0.02MB

Have your answers to these questions and or the documents you are sending today been reviewed, changed or amended by anyone?

No

Files

Please attach all Facility Repair Orders.

Please attach all Photos.



Date and time photographed

Photographer Name

Sean O'Connor



Date and time photographed

Photographer Name

Sean O'Connor



Date and time photographed

Photographer Name

Sean O'Connor



Date and time photographed

Photographer Name

Sean O'Connor

Additional Records

Business cards, photo of company vehicles onsite, etc.

Screenshot_1-10-2024_946_.jpeg, 0.12MB

Reference Number

N2427573

Incident Time: (24hr) 12:29

Incident Date: 9/24/2024

Incident Location:

City/County: Los Angeles/Los Angeles

Address/Location: 1226 W 70th St

Incident Cause: Excavation Damage

Gas Equipment Affected: Service

Material: Plastic Pipe size: ½"

Dig In Information:

USA notification required: **Yes / No**

USA notified: **Yes / No** USA #

Facilities properly marked: **Yes / No**

Name of Excavator: Selvin Ramirez Plumbing

Excavator Contact Person: Selvin Ramirez

Phone: 3234238740

On Scene:	Date	Time
Company Personnel on Scene	<u>9/24/2024</u>	<u>13:20</u>
Gas Flow Stopped	<u>9/24/2024</u>	<u>14:00</u>

Customer Outages (Quantity) 0

Summary of incident: 3rd party contractor trenching to install sewer lateral for ADU build struck and damaged ½" plastic service with chipping gun resulting in gas escape.

This document is not a certified record of Underground Service Alert

MBRCOD 00000 USAS 09/24/24 15:28 A242680858-01A EMER DMGE POLY

Ticket : A242680858 Rev: 01A Created: 09/24/24 15:28 User: LNR Chan: 100
Work Start: 09/24/24 15:28 Legal Start: 09/26/24 17:01 Expires: 10/22/24 23:59
Response Required: N Priority: EMER

Excavator Information

Company: SELVIN RAMIREZ PLUMBING
Co Addr: UNK
City : State: CA Zip:
Created By: H/O LAURENT, DWAYNE Language: ENGLISH
Office Phone: 213-509-0868 SMS/Cell: 213-509-0868
Office Email: DEEBUILZ@YAHOO.COM

Site Contact: SELVIN RAMIREZ

Site Phone: 323-423-8740 SMS/Cell: 213-509-0868
Site Email: DEEBUILZ@YAHOO.COM

Excavation Area

State: CA County: LOS ANGELES Place: LOS ANGELES
Zip: 90044

Location: **WORK HAS ALREADY STARTED**

Address/Street : 1226 W 70TH ST

: X/ST 1 : S BUDLONG AVE

: X/ST 2 :

: **WORK HAS ALREADY STARTED**

Delineated Method: NONE

Work Type: INSTALL SEWER LINE FOR ADU

Work For : H/O LAURENT, DWAYNE

Hash Tags:

Comments:

DAMAGEA DAMAGED LINE FOR GAS - DAMAGED GAS LINE AT
ADDRESS, LINE WAS REPAIRED BY GAS COMPANY ALREADY PER H/O
LAURENT, DWAYNE--[LNR 09/24/2024 03:28:00 PM]

Exhibit 2

No-Ticket Damage Reporting Form

Submitted Time: November 18, 2024 8:49 PM

Provide your name, title, phone number, and email address

Name

Selvin

Title

Plumber

Phone Number

323-423-8740

Email Address

selvin.ramirez@yahoo.com

Please provide the identifying information for SELVIN RAMIREZ PLUMBING in general.

California Contractor's State License Board (CSLB) license

N/A

Physical Address

941 e vernon ave

Mailing Address

941 e vernon ave

Phone Number

323-423-8740

Email Address

selvin.ramirez@yahoo.com

Did SELVIN RAMIREZ PLUMBING damage the NaturalGas facility while excavating at 1226 W 70th St, Los Angeles on the 9/24/2024? (Select One)

Yes

Were there any other companies at or near 1226 W 70th St, Los Angeles on 9/24/2024? (Select One)

No

Did someone in SELVIN RAMIREZ PLUMBING, or anyone else, contact the Regional Notification Center on 9/24/2024?

No

Did SoCalGas respond after the Regional Notification Center created the 811 ticket?

Is SELVIN RAMIREZ PLUMBING aware that it needed to contact the Regional Notification Center prior to excavating?

No

Did the Regional Notification Center create an 811-ticket for 1226 W 70th St, Los Angeles that SELVIN RAMIREZ PLUMBING worked?

No

If no one at SELVIN RAMIREZ PLUMBING, or anyone else, contacted the Regional Notification Center before excavating, why not?

Other

Explain why SELVIN RAMIREZ PLUMBING did not obtain an 811 ticket?

I didn't know what number to call and I'm still learning.

Has SELVIN RAMIREZ PLUMBING ever obtained an 811 ticket, either by calling 811 or using the Regional Notification Center's website?

No

The damage notification indicated that a facility was damaged at 1226 W 70th St, Los Angeles on 9/24/2024. Is that correct?

Yes

Was SELVIN RAMIREZ PLUMBING the prime contractor on the project at 1226 W 70th St, Los Angeles on 9/24/2024?

Yes

What was mentioned or what direction did the prime contractor provide to you?

Provide the names, phone numbers, and if applicable, their email address for all your personnel who were at 1226 W 70th St, Los Angeles when the facility was damaged.

Name

Selvin Ramirez

Title

Plumber

Phone Number

323-423-8740

Email Address

selvin.ramirez@yahoo.com

Add an additional individual?

Yes

Name

Jose Ramirez

Title

Apprentice

Phone Number

323-287-4107

Email Address

jdramirez7@icloud.com

Add an additional individual?

No

Which one of the individuals you identified was the foreman on the project when the facility was damaged?

Selvin Ramirez

Facility Damage

Was a facility damaged on 9/24/2024?

Yes

Describe the damaged facility.

Pinched the gas line.

Identify the type of material damaged.

Plastic gas line

Explain how the facility was damaged?

Pinched with shovel.

What equipment did SELVIN RAMIREZ PLUMBING use on 9/24/2024? (Select All That Are Applicable)

Shovel

What type of equipment damaged the facility?

Shovel

Who was operating the equipment that damaged the facility on 9/24/2024?

Jose Ramirez

Does SELVIN RAMIREZ PLUMBING own that equipment?

Yes

Emergency Response

How did SELVIN RAMIREZ PLUMBING learn that the SoCalGas facility was damaged on 9/24/2024?

The smell of gas.

Did anyone with SELVIN RAMIREZ PLUMBING call 911 on 9/24/2024 after the damage had occurred?

No

Was there an emergency response to the incident from the fire department, a law enforcement department, or an ambulance on 9/24/2024?

No

Were there any injuries to any personnel or bystanders on 9/24/2024?

No

Were there any fatalities on 9/24/2024 or afterwards, due to the damage at 1226 W 70th St, Los Angeles?

No

Was there property damage on 9/24/2024, excluding the facility damage?

No

Was there a fire on 9/24/2024 as a result of the damage to the facility?

No

Was there an evacuation of any homes or businesses on 9/24/2024 as a result of the damage to the facility?

No

Are you aware of anyone else that called 911?

No

Did anyone at SELVIN RAMIREZ PLUMBING contact the Regional Notification Center after the damage on 9/24/2024?

No

Did anyone at SELVIN RAMIREZ PLUMBING contact SoCalGas after the damage?

No

What steps, if any, have SELVIN RAMIREZ PLUMBING taken to prevent a similar damage in the future?

Contact 811 before excavating.

Is there any other information you want to share about this damage?

No

Exhibit 3

811 ticket request N2427573

From Barton, Angel@EnergySafety <Angel.Barton@energysafety.ca.gov>
Date Wed 11/6/2024 2:29 PM
To Amber Dahl <amber@digalert.org>
Cc Alcantar, Daysi@EnergySafety <Daysi.Alcantar@energysafety.ca.gov>

Good afternoon Amber,

Please provide a copy of all tickets, revisions, and electronic positive responses at about 1226 West 70th Street., Los Angeles CA, from cross-streets Budlong Avenue to Raymond Avenue, for August 24, 2024 to October 10, 2024.

If there is not a ticket at this location for any of these dates, please confirm that finding.

Cordially,

Angel Barton

Investigator

Underground Infrastructure Directorate

Phone: (916) 216-0251

www.energysafety.ca.gov



OFFICE OF ENERGY
INFRASTRUCTURE
SAFETY

Stay connected and informed by signing up for the [Underground Safety Board's subscriber list](#).

Exhibit 4

From: [Amber Dahl](#)
To: [Barton, Angel@EnergySafety](mailto:Barton_Angel@EnergySafety)
Cc: [Alcantar, Daysi@EnergySafety](mailto:Alcantar_Daysi@EnergySafety)
Subject: File N2427573
Date: Thursday, November 7, 2024 12:16:12 PM
Attachments: [N2427573.pdf](#)

CAUTION: This email originated from outside of the organization. Do not click links or open attachments unless you recognize the sender and know the content is safe.

Thank you,



Amber Dahl, Safety Director
Underground Service Alert of Southern California
PO BOX 77070 Corona, CA 92877
P: 951-808-8115 F: 951-808-8101
E: amber@digalert.org W: www.digalert.org



This e-mail message may contain confidential or legally privileged information and is intended only for the use of the intended recipient(s). Any unauthorized disclosure, dissemination, distribution, copying or the taking of any action in reliance on the information herein is prohibited. E-mails are not secure and cannot be guaranteed to be error free as they can be intercepted, amended, or contain viruses. Anyone who communicates with us by e-mail is deemed to have accepted these risks. Underground Service Alert of Southern California is not responsible for errors or omissions in this message and denies any responsibility for any damage arising from the use of e-mail. Any opinion and other statement contained in this message and any attachment are solely those of the author and do not necessarily represent those of the company.



Underground Service Alert

of Southern California™

November 7, 2024

Angel Barton
Underground Safety Board

File Number: N2427573

Dear Angel,

After searching our records from 8/24/24 through 10/10/24, we found the following DigAlert ticket(s) A242680858 for the location at or near 1226 W 70th St x/sts Budlong Ave to Raymond Ave in Los Angeles. I hope this information will be helpful.

If we can be of further assistance, please call us at 951-808-8100.

Sincerely,

Amber Dahl
Safety Awareness Director

MBRCOD 00001B USAS 11/06/24 14:33:02 A242680858-00A NEW RUSH POLY LREQ

Ticket: A242680858 Rev: 00A Created: 09/24/24 15:27 User: LNR Chan: 100

Work Start: 09/24/24 15:20 Legal Start: 09/26/24 17:01 Expires: 10/22/24 23:59
Response required: Y Priority: 0

Excavator Information

Company: SELVIN RAMIREZ PLUMBING Type: CONT
Co Addr: UNK
City : State: CA Zip:
Created By: H/O LAURENT, DWAYNE Language: ENGLISH
Office Phone: 213-509-0868 SMS/Cell: 213-509-0868
Office Email: DEEBUILZ@YAHOO.COM

Site Contact: SELVIN RAMIREZ
Site Phone: 323-423-8740 Site SMS/Cell: 213-509-0868
Site Email: deebuilz@yahoo.com

Excavation Area

State: CA County: LOS ANGELES Place: LOS ANGELES
Zip: 90044
Address : 1226 Street: W 70TH ST
Cross 1 : S BUDLONG AVE
Cross 2 :
Location: **WORK HAS ALREADY STARTED**
Searchable Tags:
Job size: sq-feet: 44725 sq-miles: 0.001604

Delineated Method: NONE

Work Type: INSTALL SEWER LINE FOR ADU

Work For : H/O LAURENT, DWAYNE

Permit: NOT AVAILABLE Job/Work order:

Project ID:

Project Name:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N Pavement Only: N

Lat/Long

Center Generated (NAD83): 33.976335/-118.297148 33.976333/-118.296526
: 33.975601/-118.297150 33.975599/-118.296528

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=CD9v8q9xCo2wtz0-j

Members:

ATTDSOUTH CHP01 CITYLASTLI LAWP3 SCG3Z2 UCHTRW_C4

(c) Copyright 2022 Underground Service Alert of Southern California.
All rights reserved.

Ticket Responses for: A242680858-00A

Member	Name	Rev	Responded	By	Response
CITYLASTLI CITY OF LOS ANGELES 00A	09/26/24	05:01:30	PM	Late Notice (999)	Member did not respond by the required time

MBRCOD 00001B USAS 11/06/24 14:33:04 A242680858-01A DMGE EMER POLY LREQ

Ticket: A242680858 Rev: 01A Created: 09/24/24 15:28 User: LNR Chan: 100

Work Start: 09/24/24 15:28 Legal Start: 09/26/24 17:01 Expires: 10/22/24 23:59
Response required: N Priority: 9

Excavator Information

Company: SELVIN RAMIREZ PLUMBING Type: CONT
Co Addr: UNK
City : State: CA Zip:
Created By: H/O LAURENT, DWAYNE Language: ENGLISH
Office Phone: 213-509-0868 SMS/Cell: 213-509-0868
Office Email: DEEBUILZ@YAHOO.COM

Site Contact: SELVIN RAMIREZ
Site Phone: 323-423-8740 Site SMS/Cell: 213-509-0868
Site Email: deebuilz@yahoo.com

Excavation Area

State: CA County: LOS ANGELES Place: LOS ANGELES
Zip: 90044
Address : 1226 Street: W 70TH ST
Cross 1 : S BUDLONG AVE
Cross 2 :
Location: **WORK HAS ALREADY STARTED**
Searchable Tags:
Job size: sq-feet: 44700 sq-miles: 0.001603

Delineated Method: NONE

Work Type: INSTALL SEWER LINE FOR ADU

Work For : H/O LAURENT, DWAYNE

Permit: NOT AVAILABLE Job/Work order:

Project ID:

Project Name:

1 Year: N Boring: N Street/Sidewalk: N Vacuum: N Explosives: N Pavement Only: N

Lat/Long

Center Generated (NAD83): 33.976335/-118.297148 33.976333/-118.296526
: 33.975601/-118.297150 33.975599/-118.296527

Excavator Provided:

Map link:

https://newtin.digalert.org/newtinweb/map_tkt.nap?TRG=DD9r9pBr1zx0pDk-2

Comments:

DAMAGEA DAMAGED LINE FOR GAS - DAMAGED GAS LINE AT ADDRESS, LINE WAS

REPAIRED BY GAS COMPANY ALREADY PER H/O LAURENT, DWAYNE--[LNR 09/24/2024
03:28:00 PM]

Members:

ATTDSOUTH CHP01 CITYLASTLI LAWP3 SCG3Z2 UCHTRW_C4

(c) Copyright 2022 Underground Service Alert of Southern California.
All rights reserved.

Ticket Responses for: A242680858-01A

Member	Name	Rev	Responded	By	Response	Comment
ATTDSOUTH	AT&T - DISTRIBUTION	01A	09/24/24 03:51:27 PM	UQ Responder	(004) NO MARKINGS REQUESTED	
CHP01	CITY OF HUNTINGTON PARK	01A	09/25/24 08:24:50 AM	emontanez	(001) CLEAR - NO CONFLICT	
LAWP3	LADWP - WTR & PWR	01A	09/26/24 07:35:36 AM	TMS:RPEREZ	(010) LOCATE AREA MARKED	Marked no conflict wtr/pwr
LAWP3	LADWP - WTR & PWR	01A	09/24/24 03:33:58 PM	TMS:RPEREZ	(004) NO MARKINGS REQUESTED	Requesting gas co response only
SCG3Z2	SOCALGAS DISTRIBUTION CRENSHAW	01A	09/25/24 09:14:55 AM	PRSDG01 DFONG	(010) LOCATE AREA MARKED	
UCHTRW_C4	SPECTRUM - BELLFLOWER	01A	09/24/24 03:51:27 PM	UQ Responder	(004) NO MARKINGS REQUESTED	