



September 17, 2025

Dan Marsh  
Senior Manager, Rates and Regulatory Affairs  
Liberty Utilities  
701 National Ave  
Tahoe Vista, CA 96148

## NOTICE OF VIOLATION

Mr. Marsh:

Pursuant to Public Utilities Code section 326 and Government Code section 15475.1, the Office of Energy Infrastructure Safety (Energy Safety) has conducted an inspection of work completed by Liberty Utilities (LU) in accordance with its 2024 Wildfire Mitigation Plan (WMP) and determined the existence of a violation. Energy Safety therefore issues LU a Notice of Violation (NOV), identifying noncompliance with an approved WMP or any law, regulation, or guideline within the authority of the Office.<sup>1</sup>

On May 8, 2025, Energy Safety conducted an inspection of Liberty Utilities' WMP initiatives in the vicinity of the city of Olympic Valley, California. The inspection report is enclosed herewith. Energy Safety found the following violation(s):

Violation 1. Energy Safety observed that in implementing 2024 WMP initiative 8.1.2.12 -Tree attachment Removals, LU failed to complete work on pole ID 81315, Grid Hardening ID d082c49c-b01f-4e34-929a-8d171ee00dc7 at coordinates 39.2010571701618, -120.232169340005. Energy Safety considers this completeness violation to be in the Minor risk category.

---

<sup>1</sup> Cal. Code Regs., tit. 14, section 29302(b)(2)

## Response Options

Energy Safety may prescribe a timeframe for resolution of a violation associated with the assigned risk category.<sup>2</sup> Within 30 days from the issuance date of this NOV, the electrical corporation must provide a response advising Energy Safety of corrective actions taken or planned to remedy the above identified violation(s) and prevent recurrence. Alternatively, the electrical corporation must advise Energy Safety that it will not correct the violation, including the reasoning or justification for inaction and all supporting documentation.<sup>3</sup>

This response shall be filed in the Energy Safety e-Filing system under the 2024 NOV Docket<sup>4</sup> and the associated file name(s) must begin with the NOV identification number provided above.

Pursuant to Government Code section 15475.4, if the electrical corporation intends to request a hearing “to take public comment or present additional information,” it must also do so within the 30-day timeframe. If a petition for hearing is not received by the deadline, then the determination and conditions set forth in this NOV become final.

Prior to its response or request for hearing, the electrical corporation may also request an informal conference with Energy Safety’s Compliance Assurance Division for the purpose of disputing any issues raised in this NOV no later than five (5) business days before the response deadline.<sup>5</sup> Requests for informal conference with Energy Safety must be e-mailed to [compliance@energysafety.ca.gov](mailto:compliance@energysafety.ca.gov), with a copy sent to all Energy Safety Compliance Assurance Division staff identified in the NOV.

Pursuant to Public Utilities Code section 8389(g), following receipt of the electrical corporation’s response to this NOV and resolution of any disputes, this matter may be referred to the California Public Utilities Commission for its consideration of potential enforcement action, as it deems appropriate.

Sincerely,



Patrick Doherty  
Program Manager | Compliance Assurance Division  
Office of Energy Infrastructure Safety  
[Patrick.Doherty@energysafety.ca.gov](mailto:Patrick.Doherty@energysafety.ca.gov)

Cc:

Peter Stoltman, Liberty Utilities  
[Peter.Stoltman@libertyutilities.com](mailto:Peter.Stoltman@libertyutilities.com)

---

<sup>2</sup> Energy Safety Compliance Guidelines, pp. 3

<sup>3</sup> Energy Safety Compliance Guidelines, pp. 4-5

<sup>4</sup> <https://efiling.energysafety.ca.gov/EFiling/DocketInformation.aspx?docketnumber=2024%20NOV>

<sup>5</sup> Energy Safety Compliance Guidelines, p. 4

Jordan Parrillo, Liberty Utilities

[Jordan.Parrillo@libertyutilities.com](mailto:Jordan.Parrillo@libertyutilities.com)

Cecilia Yaniz, Energy safety

[Cecilia.Yaniz@energysafety.ca.gov](mailto:Cecilia.Yaniz@energysafety.ca.gov)

Babak Kaviani, Energy Safety

[Babak.Kaviani@energysafety.ca.gov](mailto:Babak.Kaviani@energysafety.ca.gov)

Yana Loginova, Energy Safety

[Yana.Loginova@energysafety.ca.gov](mailto:Yana.Loginova@energysafety.ca.gov)

Samuel Isaiah, Energy Safety

[Samuel.Isaiah@energysafety.ca.gov](mailto:Samuel.Isaiah@energysafety.ca.gov)

Shannon Greene, Energy Safety

[Shannon.Greene@energysafety.ca.gov](mailto:Shannon.Greene@energysafety.ca.gov)

[Compliance@energysafety.ca.gov](mailto:Compliance@energysafety.ca.gov)



# INSPECTION REPORT

## Overview

### Inspection Categories

The Office of Energy Infrastructure Safety (Energy Safety) conducts inspections to verify the work performed by an electrical corporation as reported in an approved Wildfire Mitigation Plan (WMP) or subsequent filing, and to assess general conditions of electrical infrastructure that may adversely impact an electrical corporation's wildfire risk.

A Notice of Violation (NOV) is issued for any instances of noncompliance discovered during an inspection related to an electrical corporation's execution of its WMP initiatives.

### Correction Timelines

Violations must be corrected in a timely manner. Energy Safety may prescribe a timeframe for resolution of a violation. If Energy Safety assigns a risk category to a violation, an electrical corporation must correct the violation as required per the timelines provided in Table 1.<sup>6</sup>

**Table 1. Risk Category and Correction Timelines**

Risk Category	Violation and defect correction timeline
Severe	<ul style="list-style-type: none"><li>• Immediate resolution</li></ul>
Moderate	<ul style="list-style-type: none"><li>• 2 months (in High Fire Threat District (HFTD) Tier 3)</li><li>• 6 months (in HFTD Tier 2)</li><li>• 6 months (if relevant to worker safety; not in HFTD Tiers 2 or 3)</li></ul>
Minor	<ul style="list-style-type: none"><li>• 12 months or resolution scheduled in WMP update</li></ul>

---

<sup>6</sup> Energy Safety Compliance Guidelines, p. 3



# Inspection Summary

Table 2 provides a summary of the selection of the WMP inspection location and initiative. Table 3 provides a summary of the violation(s) found during the inspection. Details regarding the inspection that identified the violation(s) are provided in the Inspections Details Section below.

***Table 2: Inspection Location and Initiative Summary***

Electrical Corporation:	Liberty Utilities
Report Number:	CAD_LU_CYA_20250508_1021
Inspector:	Cecilia Yaniz
WMP Year Inspected:	2024
Quarterly Data Report (QDR) Referenced:	Quarter 3 (Q3)
Inspection Selection:	Energy Safety viewed the contents of the Q3 QDR and performed an analysis that resulted in the selection of the WMP initiatives and locations referenced in this report.
Relevant WMP Initiative(s):	8.1.2.12 - Tree attachment removals
Date of inspection:	May 8, 2025
City and/or County of Inspection:	Olympic Valley, Placer County
Inspection Purpose:	Assess the accuracy of Liberty Utilities' QDR data, completeness of its work, compliance with WMP requirements, and compliance with its protocols.

***Table 3: WMP Inspection Violation(s)***

Violation #	Structure ID	Grid Hardening ID	Lat/Long	HFTD	Initiative Number	Violation Type	Severity	Violation Description
Violation 1	81315	d082c49c-b01f-4e34-929a-8d171ee00dc7	39.2010571701618, -120.232169340005	Tier 2	8.1.2.12 - Tree attachment removals	Completeness	Minor	Failed to complete work on tree attachment removal

# Inspection Details

## **Violation 1:**

### **Relevant Requirement:**

LU's WMP states the following regarding initiative number 8.1.2.12 - Tree attachment removals:

1. "Liberty is removing conductors from trees and resetting to a new pole with modern materials and specifications. This initiative reduces ignition risk by removing conductors from trees and providing proper insulation."<sup>7</sup>

### **Finding:**

On pole ID 81315, Grid Hardening ID d082c49c-b01f-4e34-929a-8d171ee00dc7 at 1687-1783 Sandy Way, Olympic Valley, CA, 96146, USA, 39.2010571701618, -120.232169340005, the inspector observed that the tree attachment was present on the tree. The inspector's observation is documented in Violation 1 photographs, which are attachments to this report. Photo numbers Item1IA1Img1, Item1IA1Img2 depict incomplete removal of a tree attachment. In the 2024 Q3 Quarterly Data Report submission, LU reported that work on 8.1.2.12 – Tree attachment removals were completed at this location.

Energy Safety concludes that there is a violation because of these facts:

1. A tree attachment was observed on the tree at this location.
2. The conductor is present at the tree attachment point.
3. A new pole with modern materials and specifications was not observed at this location.

---

<sup>7</sup> Liberty Utilities, "Liberty 2023-2025 Wildfire Mitigation Plan" August 9, 2024, p. 174. [Online]. Available: <https://efiling.energysafety.ca.gov/eFiling/Getfile.aspx?fileid=57172&shareable=true>



# Exhibits

Exhibit A: Photo Log

Structure ID: 81315


Violation 1



Item1GImg1: Overall Pole



Item1GImg2: Pole ID



Item1IA1Img1: Conductor from pole to tree attachment



Item1IA1Img2: Conductor installed to tree attachment